





GEOTECHNICAL DATA

-  AREAS OF FILL
-  AREAS OF SLOPE INSTABILITY
-  QUARRY SLOPE SETBACK
-  FAULT T ZONE BOUNDARY

GEOTECHNICAL DATA AS SHOWN
 PER REPORT PREPARED BY
 GIBLIN ASSOCIATES DATED
 OCTOBER 13, 2005



**OAT HILL PROPERTIES
 GEOTECHNICAL CONSTRAINTS MAP
 NAPA COUNTY
 CALIFORNIA**